

Division of Oil, Gas, & Mining
Mining Report

08/15/96

MINE ID: M0150014

MINE NAME: FOUR CORNERS

OPERATOR: SAN RAFAEL ENERGY CORP
CONTACT: GARY L. JACOBSON
ADDRESS: P O BOX 805
MOAB UT 84532

PHONE: (801)259-5961

Surface Owner: BLM
Mineral Owner: BLM

BLM #:
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
	E2	NW				22	21.0S	14.0E

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: U

Mine Status: SUS

Acreage: 1

Status Date: / /

Minerals Mined
U

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

06/20/77

10/28/82

01/27/84

07/19/96

BOND TYPE: CERTIFICATE DEPOSIT

BOND AMOUNT: \$\$\$\$\$\$7,000

ANNUAL REPORT YEAR: 95

	YTD	Total					
NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
VIOLATIONS:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
REVISIONS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/
AMENDMENTS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/

COMMENTS:

Quick site visit made to briefly evaluate reclamation success on the site. Portions of the site were reclaimed about two years ago and seeded. Operator wanted to reduce size of disturbance and bond. Several waste dumps were regraded and reseeded. No successful revegetation on site at this inspection. MINE OFFICE, SHED, WAREHOUSE & MINE PORTAL LEFT TO BE RECLAIMED. DOGM CAN RELEASE A PORTION OF THE \$7,000 BOND, BUT NOT ENTIRELY UNTIL ALL OUTSTANDING ISSUES HAVE BEEN RECLAIMED. 96 VISIT STILL NEEDS REVEGETATION SUCCESS.